









1 – Pictorial Guide to Gears



1 GEARS

Description	Configuration
Gear Stock, Pinion Wire, Pinions & Pinion Shafts	
Hubless & Hubbed Gears, Machined & Molded Gears	
Fairloc® Hub, Anti-Backlash Internal & Helical Gears	
Gear Blanks, Racks, Flexiracks & Guides	
Miter, Bevel, Worm Gears & Worms	
Molded Worm Gears, Molded Worms, Splines & Ratchets	



GEAR LOCATOR CHART – METRIC 1-2

GROUND SPUR GEARS 1-6

PINIONS 1-17

SPUR GEAR STOCK 1-22

PINION WIRE 1-24

METALLIC SPUR GEARS 1-25

NONMETALLIC SPUR GEARS

 Machined 1-94

 Molded 1-111

ANTI-BACKLASH GEARS 1-124

HELICAL GEARS 1-126

INTERNAL GEARS 1-126

RACKS 1-128

MITER AND BEVEL GEARS 1-138

WORM GEARS & WORMS 1-147

HUBS FOR GEARS & DIALS 1-160

GEAR BLANKS 1-163

SPLINES & BUSHINGS 1-165

RATCHETS 1-168